

RELEASE NOTES

CONSOLE® AI Software and Firmware

PRODUCTS SUPPORTED:

CONVERGE® Pro 2
CONVERGE® Huddle
BMA 360, BMA CT, BMA CTH, BMA 2
CONVERGE® Bluetooth Expander
CONVERGE® USB Expander
CONVERGE® GPIO Expander
COLLABORATE® Versa Lite CT and Versa Room CT
DIALOG® 20 Wireless Mics
CONVERGENCE™ AV Manager

September 11, 2024

RELEASE 09.11.2024

CONSOLE AI v7.7.1.6

What's New

1. Camera Auto Tracking Enable/Disable now works correctly in macros.
2. Camera preset macros are now working as expected.
3. Various bug fixes.

CP2 v8.7.14.17

What's New

1. Resolved issues affecting Google Meet functionality.
2. Fixed several issues involving beam rotation.
3. A rotated beam pattern now correctly reports switching.

Huddle v8.6.9.0

What's New

1. Resolved issues affecting Google Meet functionality.
2. Restoring the unit to factory default now properly restores routing for BMA CT mic and speaker channels.
3. Added support for a new hardware version.

USB Expander v1.0.2.11

What's New

1. Resolved issues affecting Google Meet functionality.

RELEASE 03.26.2024

CONSOLE AI v7.7.0.14

What's New

1. Macros have been optimized with improved execution performance.
2. New macro commands to call camera presets and set auto tracking on/off.
3. Fixed issue where the FILTER ENABLE macro command was not working on the CP2 unit.
4. Fixed issue where the Speaker Bridge mode on the BMA 360 was not being saved.
5. Fixed issue in the Manual Control panel where the last preset run display was off by 1.
6. Fixed issue where ALC could not be enabled on a 128SR or 128SRD unit.
7. Device temperature warnings have been added to the discovery window.
8. Stability and GUI improvements.
9. Various bug fixes.

CP2 v8.7.14.13

What's New

1. Big improvements in robustness and reliability with redundant data backups and automatic data recovery.
2. Macro execution optimization allows many macros to be called quickly.
3. GPIO improvements provide reliable and efficient execution with many simultaneous GPIO changes.
4. Fixed an issue where the GPIO output pins may intermittently be asserted incorrectly after a project load, power cycle, or preset execution.
5. Added support for the new DIALOG 20 USB wireless microphone.
6. Fixed a rare occurrence of corrupted audio being heard on the USB audio.
7. Fixed a rare issue where some audio channels would produce a noise in some channels.
8. Fixed issue with the microphone ALC not being enabled/disabled correctly.
9. Added the ability to allow the BMA 360 camera control logic to use both gating and beam selection simultaneously.
10. Various bug fixes.

Huddle v8.6.6.1

What's New

1. Big improvements in robustness and reliability with redundant data backups and automatic data recovery.
2. Added support for a new hardware revision.
3. Fixed an issue that when the "Clear All Crosspoints" button was pressed, the crosspoints to the Mobile channels were not cleared.
4. Various bug fixes.

BMA 360 v1.0.8.4

What's New

1. Fixed issue where Speaker 1 would not pass audio on some units.
2. Added support for new hardware revision.

BMA CT v2.0.0.5

What's New

1. Added feature for improving the manufacturing process.

RELEASE 09.29.2023

CP2 v8.6.16.59

What's New

1. Improved reliability for firmware upgrades
2. Fixed issue with 128SR/SRD units where audio may begin to have artifacts

RELEASE 09.21.2023

CONSOLE AI v7.6.3.2

What's New

1. Fixed issue with cross points being removed when running a preset in another partition. Requires FW v8.6.16.50 or newer.
2. Loading a file that sets a CP2 or Huddle unit to a static IP address is handled better.
3. Several crash fixes.

CP2 v8.6.16.56

What's New

1. Fixed issue where the AEC would not work properly on some units.
2. Improvements to the BMA 360 VL voice lift gating group logic.
3. Fixed issue with cross points being removed when running a preset in another partition. Requires CONSOLE AI v7.6.3.2 or newer.
4. Added warning to wait 30 seconds when issuing the shutdown prep command.
5. USB audio stability improvements. Fixed issue with audio going away when the USB cable is repeatedly plugged and unplugged.
6. Mute Synch with MS Teams functionality has been restored.
7. Stability improvements.
8. Various bug fixes.

Known Issues

1. When a Custom Reference is being used on an output, changes to any output settings such as mute, gain, or polarity, may cause the echo canceller to perform poorly.
2. Loading a file for the first time may take longer than normal.

Huddle v8.6.3.5

What's New

1. USB audio stability improvements. Fixed issue with audio going away when the USB cable is repeatedly plugged and unplugged.

USB Expander v1.0.2.9

What's New

1. USB audio stability improvements. Fixed issue with audio going away when the USB cable is repeatedly plugged and unplugged.

BMA CT v2.0.0.3

What's New

1. Added support for new LED board.

BMA CTH v2.0.0.3

What's New

1. Added support for new LED board.

RELEASE 06.29.2023

CP2 v8.6.16.44

1. Fixed issue with speaker filters causing artifacts when set to a frequency less than 100 Hz.
2. Fixed issue with GPIO Expanders being disabled when added to the 2nd CP2 in the stack.
3. Fixed issue with USB transmit audio going away after multiple USB cable unplug/plug events. The tradeoff is that Mute Sync with MS Teams no longer functions in either direction.
4. During the next firmware upgrade, any configured static IP address will be preserved. Upgrading from any previous version to this version will discard the static IP address and revert to DHCP.
5. Reject TELNET sessions during startup to prevent the unit from being overloaded with messages from a 3rd party device.
6. Added support for new Dante hardware modules.

Huddle v8.6.3.3

1. Enables all CONVERGE Huddle units to be used with a BMA CTH.
2. During the next firmware upgrade, any configured static IP address will be preserved. Upgrading from any previous version to this version will discard the static IP address and revert to DHCP.
3. Reject TELNET sessions during startup to prevent the unit from being overloaded with messages from a 3rd party device.

BMA 360 v1.0.8.0

1. Fixed rare issue with some Speaker outputs having intermittent pops and clicks.

BMA CT v2.0.0.0

1. Makes the BMA CT compatible with a CONVERGE Huddle and Versa Lite CT. Use a CP2 to upgrade the BMA CT.
2. Support for additional hardware revision.

BMA CTH v2.0.0.0

1. Makes the BMA CTH compatible with a CONVERGE Pro 2. Use a Huddle to upgrade the BMA CTH.
2. Support for additional hardware revision.

CONSOLE AI v7.6.2.1

1. Stability improvements

RELEASE 04.27.2023

CONSOLE AI v7.6.1.1

1. Fixed an issue when using a touchscreen to add or manipulate items in the FlowView window.
2. Fixed issue when connecting to a new Huddle that sometimes told the user to Factory Default the unit.

RELEASE 04.18.2023

CONSOLE AI v7.6.0.50

1. Added support for 3 new features:
 - Native Camera Tracking in CP2
 - Custom Beam Pointing
 - Chairman Gating Ducker
2. GUI improvements.
3. Various bug fixes.
4. Fixed several issues that caused the software to crash.

CP2 v8.6.16.36

1. Added support for 3 new features:
 - Native Camera Tracking in CP2
 - Custom Beam Pointing
 - Chairman Gating Ducker
2. Fixed issue with macro and command execution being slow in the previous firmware release.
3. Fixed issue with some computers becoming slow or unresponsive with Microsoft Teams installed and connected to the CP2 USB Audio port. The trade-off is that Mute Sync is no longer functioning from the CP2 to MS Teams—the plan is to reinstate the Mute Sync in a future release.
4. Fixed intermittent issue with USB audio going away when the USB cable was disconnected and

reconnected while playing audio.

5. Significantly decreased the occurrence of an issue where Windows may report an unrecognized device when connecting the USB audio cable.
6. Some Windows computers may exhibit choppy audio when connected to the USB audio port of the CP2. This can usually be fixed by placing a USB hub between the computer and the CP2 or by disabling the “Intel® Smart Sound Technology for USB Audio” driver found under “Sound, video, and game controllers” in the Windows Control Panel.
7. Various bug fixes

Huddle v8.6.2.12

1. Fixed issue with the USB connection where the attached computer would not go to sleep.
2. Fixed issue with the Huddle not being discovered via Ethernet when configured with a static IP address.
3. Fixed issue with the front panel USB connection not being reported reliably.
4. Fixed issue with the Locate button not working in the CONSOLE AI discovery window.
5. Fixed issue that prevented upgrading the BMA CTH.
6. Fixed issue with Bluetooth Expander upgrade.
7. Added support for additional hardware revision.
8. Various bug fixes.

BMA 360 v1.0.7.9

1. Fixed issue with Pre and Post Gain meters not working if Beam 1 is disabled and Last Beam On is disabled.

RELEASE 12.19.2022

CONVERGE Pro 2 v8.5.18.5

1. Added support for additional BMA 360 hardware revision.

BMA 360 v1.0.7.8

Note: You must upgrade the CP2s to v8.5.18.5 (or newer) before upgrading the BMA 360s

1. Added support for additional BMA 360 hardware revision.

RELEASE 09.06.2022

CONVERGE Huddle v8.6.1.7

1. Added support for additional hardware revision.

RELEASE 09.02.2022

CONVERGE Pro 2 v8.5.17.0

1. Fixed issue with intermittent noise and popping that may sometimes occur on the latest hardware revision.

RELEASE 02.21.2022

CONSOLE AI v7.5.4.1

1. Fixed an issue where Voice Lift channels may show incorrect routes after loading a project.
2. Fixed rare issue where the Feedback Eliminator button not be displayed in a Processing Block channel.

RELEASE 02.01.2022

CONSOLE AI v7.5.3.5

1. BMA 360 devices are now allowed in Macros
2. Fixed rare issue where CONSOLE AI may fail to load a project file.
3. Fixed issue where Voice Lift channel routing may not show correctly in the FlowView and MatrixView

CONVERGE Pro 2 v8.5.15.0

1. Fixed issue where Voice Lift channels may still pass audio even though all beams have been disabled.
2. Fixed issue when using multiple BMA 360's where one or more beamformers may mirror the audio of another beamformer.
3. Changed the behavior of the BeamReport for camera tracking so that a beam is reported as active only if the BMA 360 is gated on. If the BMA 360 is not gated on, then all beams for that beamformer will be reported as inactive in the BeamReport.
4. Fixed issue where changing P-Link cables on a BMA 360 may cause the CP2 to lock up.

RELEASE 11.01.2021

CONSOLE AI v7.5.1.7

1. Various bug fixes

CONVERGE Pro 2 v8.5.8.0

1. Various bug fixes

RELEASE 10.22.2021

CONSOLE AI v7.5.1.4

1. Added an enable for USB Audio Mute Sync for Microsoft Teams in CONSOLE AI under CP2 Device Settings
2. Fixed issue with BeamReport not reporting correctly when the beam configuration window is open in CONSOLE AI
3. Fixed issue where the Speaker Bridge Mode may not show the correct setting in CONSOLE AI when changing the mode with an external controller
4. Fixed issue where Voice Lift channel routing may not persist when more than one BMA 360 is connected to the same device
5. Fixed issue with loading project files from an older version where names and channels may not get loaded correctly

CONVERGE Pro 2 v8.4.18.0

1. Added “Enable for USB Audio Mute Sync” control to enable mute to be synced in both directions between Microsoft Teams, USB Tx, and any connected beamformers. This includes BMA 360 and all other beamformers for CP2.
2. Added Mute Sync capability to CP2 Dante units--now all CP2 units will perform Mute Sync with Microsoft Teams

RELEASE 09.06.2021

CONSOLE AI v7.5.0.16

1. Added TTLS 802.1x authentication type
2. Added TLS and SRTP VoIP protocols
3. Various bug fixes

CONVERGE Pro 2 v8.4.8.0

1. Added TTLS 802.1x authentication type
2. Added TLS and SRTP VoIP protocols
3. Added support for Microsoft Teams Mute Sync for non-Dante CP2s via the USB audio connector. Beamformers connected to the CP2 synchronize mute status. The CP2 connected to the Teams system does not synchronize mute with Beamformers connected to other CP2s in the stack.
4. A re-boot of the Microsoft Teams system may be needed.
5. BeamReport changed to support multiple Beamformers for camera tracking. BeamReport now reports only the beam of the gated-on Beamformer. If the Beamformer is not gated on, the beams are reported as inactive.
6. Various bug fixes

CONVERGE Huddle v8.4.3.0

1. Added TTLS 802.1x authentication type
2. Fixed issue with BMA CTH not muting when Safety Mute is on

BMA 360 v1.0.6.10

1. Fixed issue where Bridged mode did not return to 4x15 Watt after loading a project

RELEASE 08.31.2021

CONSOLE AI v7.4.2.0

1. Fixed CONSOLE AI crash when attempting to “Commit changes to hardware” to a CP2 via the front-panel USB connection

RELEASE 07.02.2021

CONSOLE AI v7.4.1.2

1. Added support for 802.1x with authentication types EAP-MD5, EAP-TLS, and EAP-PEAP for Huddle
2. Fixed Ref Gain for BMA CTH and Huddle
3. Fixed issue with DXF file export for Beam Patterns

Huddle v8.3.3.0

1. Added support for 802.1x with authentication types EAP-MD5, EAP-TLS, and EAP-PEAP for Huddle

Known Issues

1. Performing the firmware upgrade will restore factory defaults on the Huddle and will cause all custom settings to be lost. If you want to preserve your settings, save the project file to your hard drive first, perform the firmware upgrade, and then restore the project file.

RELEASE 06.22.2021

CONSOLE AI v7.4.0.16

1. Added support for 802.1x with authentication types EAP-MD5, EAP-TLS, and EAP-PEAP
2. Can export a single BMA 360 Coverage Pattern to a DXF file to import into a CAD drawing program
3. Added Macro and Macro Recorder support for Voice Lift channels
4. Various bug fixes

CP2 v8.3.15.0

1. Added support for 802.1x with authentication types EAP-MD5, EAP-TLS, and EAP-PEAP.
2. Support for Mute Sync with Cisco Room Kit via USB to RS-232 Adapter. Refer to App Note for details.
3. Various bug fixes

BMA 360 v1.0.6.9

1. BeamReport for camera tracking will show no beam active after two seconds of silence if “Report Last Beam On” is not checked.
2. Various bug fixes

RELEASE 05.28.2021

CONVERGE Pro 2 Firmware v8.2.13.0

1. Fixed issue with BeamReport sometimes including asterisks in the reported data

RELEASE 04.26.2021

BMA 360 v1.0.5.3

1. Improvements to the BEAMREPORT command which results in more consistent reporting of the beam containing the dominant talker.
2. Works with CONVERGE Pro 2 version v8.2.x.x (or later).

3. Works with CONSOLE AI v7.3.x.x (or later).

Known Issues

1. The BMA 360 Beam Configuration window in CONSOLE AI allows an installer to enable up to two beams to become active at a time. However, the GUI of the Beam Configuration window will only show one beam active at a time. Also, the Advanced Setting tab of the Beam Configuration window in CONSOLE AI will allow an installer to disable the Last Beam On setting. However, the GUI of the Beam Configuration window will continue to highlight the last beam that was turned on.
2. These are limitations of the current system that will be corrected in a future release.

RELEASE 03.29.2021

CONSOLE AI Software v7.3.0.16

1. Added Voice Lift Submixes to the BMA 360. A Voice Lift tab has been added to the BMA 360 Config window providing a powerful and simple way to drive multiple mix-minus speaker zones.
2. Added 'Max Active Beams' setting in the BMA 360 Advanced Tab. This can be set to either 1 or 2. A setting of 1 allows one beam on at a time and is best for most installations. A setting of 2 allows 2 beams to come on when two people are talking simultaneously.
3. Added 'Last Beam On' toggle in the BMA 360 Advanced Tab. Disabling this setting allows all beams to turn off when no one is talking.

CONVERGE Pro 2 Firmware v8.2.12.0

1. Added support for Voice Lift in the BMA 360
2. Improved echo cancellation
3. Various bug fixes

Huddle v8.1.3.0

1. Improved echo cancellation
2. Various bug fixes

BMA 360 v1.0.4.10

1. Added support for Voice Lift
2. Added Max Active Beams setting
3. Added Last Beam On setting
4. Various bug fixes

BMA CT v1.1.0.8

1. Improved echo cancellation
2. Various bug fixes

BMA CTH v1.1.0.18

1. Improved echo cancellation
2. Various bug fixes

BMA 2 Firmware v1.0.4.5

1. Improved echo cancellation
2. Various bug fixes

CONVERGENCE AV Network Manager v2.0

1. Updated configuration backup, restore, download, and upload for CP2 stacks and Huddles to use CONSOLE AI v7.3
2. Will update firmware of Huddles, CP2 stacks, and BMA P-Link peripherals to use new 'Voice Lift' and other improvements
3. Connects to CONVERGENCE™ AV CLOUD for multiple Manager server device monitoring and control aggregation
4. Facilitates instant support of users and clients with built-in video, audio, and chat tools
5. Added SMS text message alerts and an icon navigation option
6. Promoted Network settings tab to a first-class view via the navigation bar
7. Added optional automatic updates of the Manager server software and new 'Owner' user role

Known Issues

1. In the Macro editor or Macro recorder, some Voice Lift channel actions may produce an error.
2. After loading a project, a P-Link device may disappear. Power-cycle the P-Link device and the unit should re-appear.
3. When in the Project Load screen, a P-Link device may be shown as blank. Power-cycle the P-Link device and the name should re-appear.

RELEASE 11.25.2020

CONSOLE AI Software v7.2.44.0

1. Fixed BT_Rx channel crosspoints not being removed on device when cleared in CONSOLE AI
2. Fixed application crash when opening Bluetooth Device properties in a Huddle

CONVERGE Pro 2 Firmware v8.0.41.0

1. Fixed Beam Rotation not persisting in the device

CONVERGE Huddle Firmware v8.0.18.0

1. Fixed issue with default project file in a Huddle causing an application crash in CONSOLE AI

RELEASE 10.19.2020

CONSOLE AI Software v7.2.40.0

1. Added new BMA 360 ceiling tile beamforming microphone array
2. Added Reference Gain control in AEC setup page

3. Added color gradient for ERL meter to indicate proper levels
4. Added Communications Test in the Device Settings to assist with network setup
5. Added new Project Audit, Workflow Checklist items, and Quick Tips
6. Added progress bars for loading a project and upgrading firmware
7. CONSOLE AI now shows Bluetooth paired name
8. Various bug fixes

CONVERGE Pro 2 Firmware v8.0.40.0

1. Added BEAM and BEAMREPORT for BMA 360 to support camera tracking
2. Added NAPTR as a new Transport Type under VoIP settings
3. Added SSH and the ability to disable Telnet. Ability to adjust SSH and telnet timeout values via text command.
4. Added support for Reference Gain control
5. Added temperature reporting for CP2
6. Various bug fixes

BMA 360 Firmware v1.0.3.20

1. Initial Release

CONVERGE Huddle Firmware v8.0.15.0

1. Added an always-on limiter to the speaker outputs to prevent brown outs when loud audio is played
2. Added support for Reference Gain control
3. Various bug fixes

BMA 2 Firmware v1.0.4.3

1. Various bug fixes

Bluetooth Expander Firmware v1.0.1.18

1. Added support for Versa Lite CT

RELEASE 10.01.2020

BMA CT Firmware v1.1.0.5

1. Added an always-on limiter to the speaker outputs to prevent brownouts when loud audio is played.

BMA CTH Firmware v1.1.0.15

1. Added an always-on limiter to the speaker outputs to prevent brownouts when loud audio is played.

RELEASE 4.2.2020

CONVERGE Pro 2 Firmware v7.1.14.0

1. Applies to all Converge Pro 2 models
 - a. Fixed issue in which the device may stop functioning properly when using SNMP
 - b. Optimized for use with CONVERGENCE[®] AV Network Manager

CONVERGE Huddle Firmware v7.1.11.0

1. Applies to all Huddle and Versa Pro CT systems
 - a. Optimized for use with CONVERGENCE[®] AV Network Manager

RELEASE 3.16.2020

CONSOLE AI Software v7.1.18.0

1. Added optional Quick Tips about CONSOLE AI each time you open it
2. New device management screen
3. VoIP Channel Properties view includes VoIP registration status, with the last status response and registration failure status messages.
4. Log viewer enhanced with logging improvements
5. Added abilities
6. Launch the dialer application from the Channel Properties view. Launching the dialer application from the toolbar will attempt to auto connect to the last connection.
7. Place and answer Telco and VoIP calls from within the dialer application
8. Change all VoIP settings while connected, except DTMF Payload, Dial Plan, and Codec Priority
9. Disable FTP on the network ports—must use front panel USB port to connect with Console AI
10. Enable/Disable Bluetooth Expander from Console AI
11. New signal generator status and control window
12. Various bugs fixes

Converge Pro 2 Firmware v7.1.12.0

1. Corrected USB Audio Transmit level issue. Level is now more uniform across different computers and operating systems. USB transmit level may be louder and require adjustment.
2. Corrected NTP issue when multiple units in a stack are connected to the network.
3. Added ability to disable FTP on the network ports—must use front panel USB port to connect with Console AI
4. Added ability to Enable/Disable Bluetooth Expander from Console AI or 3rd party controller.
5. Various bug fixes.

Converge Huddle Firmware v7.1.8.0

1. Corrected USB Audio Transmit level issue. Level is now more uniform across different computers and

operating systems. USB transmit level may be louder and require adjustment.

2. Default Mobile Tx gain is now set to -24 dB for better audio performance with most devices.
3. Added ability to disable FTP on the network ports—must use front panel USB port to connect with Console.
4. Added ability to Enable/Disable Bluetooth Expander from Console AI or 3rd party controller.
5. Various bug fixes

Bluetooth Expander v1.0.1.17

1. Corrected low level audio that had been occurring on some devices - BT Rx gain adjusted by +18dB for headset profile.

USB Expander v1.0.2.8

1. Corrected USB Audio Transmit level issue. Level is now more uniform across different computers and operating systems. USB transmit level may be louder and require adjustment.

Known Issues

1. On a Huddle, if you load a project that changes the network settings, to see the new settings you must disconnect and reconnect.
2. After you commit changes to hardware and then disconnect, you may be prompted to commit live values again.
3. The serial port baud rate on USB Expander, GPIO Expander, and Converge Pro 2 works only at 57600.
4. If no device is playing audio, the Bluetooth Expander Receive meters may occasionally get stuck. After a device connects and begins to play audio, the meters function normally.
5. After a factory default or reset, a device occasionally may not get an IP address from the DHCP server. To remedy this, reset or power cycle the device.
6. The Touch Panel Controller updater tool may prevent Console AI from discovering devices. To remedy this, after you use the TPC updater tool, reboot your computer.
7. If you load a project file that disables the Bluetooth Expander, to see the correct status you must disconnect Console AI and then reconnect.
8. If you are running CONVERGENCE™ AV Network Manager, you may occasionally receive a message in Console AI that “A device in the stack has changed status unexpectedly.” This is an erroneous message - you can dismiss it.
9. After you load a project file to a factory defaulted system, Console AI may stay in the Load screen and not allow you to change to different views. To remedy this issue, disconnect and reconnect Console AI.

RELEASE 11.15.2019

CONSOLE AI Software v7.0.34.0

1. Replaces Pro CONSOLE
2. Support for Skype For Business has been removed
3. Configure ClearOne pro audio DSP devices using built-in Audio Intelligence to save time for AV practitioners
4. AI Workflow Checklist guides users in building systems to avoid missed steps
5. AI Project Audit checks designs and reports errors and warnings to alert of potential problems.

6. Enhanced visualization dramatically streamlines routing, design, and reviews. New visual language elements include drag-and-drop, boundary boxes, mixer blocks and custom routing lines.
7. Audio channel groups can be created – then expanded for detailed control or collapsed for simplified viewing and control.
8. In-line renaming allows label changes on channels and channel groups without going to the Renaming Tool.
9. C-Link capacity increased to 150 channels, allowing larger systems to be created.
10. Now two design modes—Simple, for single-room designs, and Advanced, to create dividers and partitions.
11. Supports ClearOne’s latest devices: Versa Pro CT and Wall-Mount Bluetooth Expander.

Converge Pro 2 Firmware v7.0.19.0

1. Requires CONSOLE AI
2. Before upgrading firmware, save the project file to disk. After upgrading firmware to v7.0.19.0 you must reload the saved project file using CONSOLE AI.
3. Support for Skype For Business has been removed
4. C-Link increased to 150 channels which allows you to build larger systems
5. Support for Bluetooth Expander
6. Various bug fixes

Converge Huddle Firmware v7.0.16.0

1. Support for CONSOLE AI
2. Support for BMA CTH and Bluetooth Expander
3. Various bug fixes

BMA 2 Firmware v1.0.4.0

1. AEC stability improvements

BMA CT Firmware v1.1.0.2

1. AEC stability improvement

BMA CTH Firmware v1.1.0.4

1. Initial release
2. Huddle-compatible Beamforming Microphone Array Ceiling Tile
3. Connects to the Expander port on the Huddle

USB Expander Firmware v1.0.2.7

1. Enforces 48 kHz sample rate for high quality audio

RELEASE 7.18.2019

CP2 Firmware v6.0.33.0

1. Fixed a potential issue with HREQ failures during a project load and during boot-up.

2. Fixed issues with the Feedback Eliminator not getting set correctly after a project load and not getting displayed correctly.
3. Fixed issue with outputs 9-12 on the 012 unit not getting configured correctly.
4. Fixed issue with an SNMP memory leak.

RELEASE 3.23.2019

Pro CONSOLE Software (v6.5.5.0)

1. New ONLINE indicator in the top toolbar when you are connected to hardware
2. Made it easier to save projects to disk and commit changes to hardware
3. Multiple Views have been removed to simplify navigation
4. New prompt tells you when you should commit changes to hardware
5. Various bug fixes

CP2 Firmware v6.0.29.0

1. Fixes for RAMP commands
1. Various bug fixes

Known Issues

1. If hardware does not match the currently loaded project you cannot use the “Commit Changes to Hardware” function until you either restore the hardware setup or disconnect and Load a project file that matches the current hardware setup. For example, if a P-Link device is disconnected you must either plug the device back in or remove the P-Link device from the project and then Load the revised project. If you activate the “Commit to Hardware” function with a hardware mismatch the function will not complete and you will need to reboot the hardware and then correct the mismatch.

After loading a project, you may need to reboot the CP2 units prior to enabling feedback elimination.

RELEASE 2.28.2019

Pro CONSOLE Software (v6.2.30.1)

1. Fixed bug that would prevent BMA CT firmware from being updated.

RELEASE 2.22.2019

Version Details

1. Pro CONSOLE® Software – v6.2.30.0 (new)
2. CONVERGE Pro 2 Firmware - v6.0.22.0 (new)
3. CONVERGE Huddle Firmware - v1.0.21.0 (same as last release)
4. BMA CT - v1.0.2.3 (new)
5. Beamforming Microphone Array 2 Firmware - v1.0.3.18 (same as last release)
6. USB Expander Firmware - v1.0.2.6 (same as last release)

7. GPIO Expander Firmware - v1.0.2.6 (same as last release)
8. DIALOG™ 20 Firmware – MDO: 2.3.5.2, RXM: 2.0.4, RXS: 1.5.0, MUX: 3.4, TX: 1.2.9 (same as last release)
9. Touch Panel Controller Firmware - v1.0.0.7 (same as last release)

New Products

BMA CT

CONVERGE Pro 2 48VTD

Pro CONSOLE Software (v6.2.30.0)

1. Support for Version 5.0.38.0 firmware or newer. Firmware prior to v5.0.38.0 forces an update.
2. Project files created prior to v6.x need to be opened and re-saved before loading into units. This will convert your file to the latest version.

New and Improved

1. New 0 to 10 millisecond audio delay in the Mic/Line Input processing.
2. New BMA CT unit.
3. New 48VTD unit.
4. More localization support.
5. ERL, ERLE, TERL meters for the BMA 2 and BMA CT.
6. Improved ClearOne Discovery Service.
7. The Replace option in the Devices screen is more stable.
8. General bug fixes

CP2 Firmware (v6.0.22.0)

1. Prior to upgrading firmware save your project file to your local hard drive because you will need to reload the project after the upgrade is complete.

New and Improved

1. New feature in the Mic/Line Input Processing: a 0-10ms audio delay.
2. Support for new BMA CT unit.
3. Support for new 48VTD unit.
4. Enhanced Long Distance P-Link Discovery (connect P-Link devices before powering up the system).
5. Improved stability with Skype for Business.
6. Network ports report a more descriptive message when they do not get a valid IP address.
7. General bug fixes

Known Issues

1. There is a rare occurrence during boot up that may require you to power cycle your units. If you are unable to load a configuration you may need to power cycle your units.
2. If you add or remove a CP2 unit via C-Link you may need to power cycle the entire stack before loading a configuration.
3. When using Long Distance P-Link mode connect the P-Link devices before powering on the CP2 units.

4. The Macro Recorder will not create a command for the BMA CT Beam Pattern.
5. Filter commands in macros that are set to a type of “None” will create an error instead of a valid command.
6. The Skype for Business Process may discontinue to register while idle--this requires a power cycle or reset to recover.
7. If Skype for Business fails to register 5 times in a row the unit will reset.
8. If the unit is already configured for Skype for Business and you re-load a configuration you must restart the CP2 to initiate a new registration.

BMA CT Firmware (v1.0.2.3)

1. Initial release.
2. Use CP2 firmware v6.0.22.0 or above.
3. New units out of the box will likely require a firmware update to v1.0.2.3.
4. Use 56V/640mA (36W) PoE Injector.

RELEASE 2.5.2019

Version Details

1. Pro CONSOLE® Software – v6.1.7.0 (same as last release)
2. CONVERGE Pro 2 Firmware - v5.0.48.0 (new)
3. CONVERGE Huddle Firmware - v1.0.21.0 (same as last release)
4. Beamforming Microphone Array 2 Firmware - v1.0.3.18 (new)
5. USB Expander Firmware - v1.0.2.6 (new)
6. GPIO Expander Firmware - v1.0.2.6 (same as last release)
7. DIALOG™ 20 Firmware – MDO: 2.3.5.2, RXM: 2.0.4, RXS: 1.5.0, MUX: 3.4, TX: 1.2.9 (same as last release)
8. Touch Panel Controller Firmware - v1.0.0.7 (same as last release)

Bugs Fixed

CONVERGE Pro 2 Firmware (v5.0.48.0)

1. USB audio level fix
2. Fixed echo issue that could occur with some web conferencing systems
3. Various AEC fixes and improvements
4. Dante secondary port allowed to switch between redundancy and switched mode
5. Fixed loss of Dante audio after a reboot
6. Fixed issue with VoIP Rx audio not working correctly on Output channels

Beamforming Microphone Array 2 Firmware (v1.0.3.18)

1. Improved beam switching
2. Fixed echo issue that could occur with some web conferencing systems

USB Expander Firmware (v1.0.2.6)

1. USB audio level fix

RELEASE 10.23.2018

Version Details

1. Pro CONSOLE® Software – v6.1.7.0 (new)
2. CONVERGE Pro 2 Firmware - v5.0.38.0 (same as last release)
3. CONVERGE Huddle Firmware - v1.0.21.0 (new)
4. Beamforming Microphone Array 2 Firmware - v1.0.3.12 (same as last release)
5. USB Expander Firmware - v1.0.2.5 (same as last release)
6. GPIO Expander Firmware - v1.0.2.6 (same as last release)
7. DIALOG™ 20 Firmware – MDO: 2.3.5.2, RXM: 2.0.4, RXS: 1.5.0, MUX: 3.4, TX: 1.2.9 (same as last release)
8. Touch Panel Controller Firmware - v1.0.0.7 (same as last release)

Bugs Fixed

CONVERGE Huddle Firmware (v1.0.21.0)

1. Fixed First Mic Priority bug.
2. Lowered Telnet timeout back to 10 minutes.
3. Fixed USB audio level bug.

Pro CONSOLE Software (v6.1.7.0)

1. Various language bugs fixed.
2. Locate indicator clears when device goes offline.
3. Fixed issue with Standard References on Speaker channels.
4. Last Mic Mode “Last On” mode issue fixed.
5. Several issues fixed when loading project files created on an older version.
6. Several connection and stability issues fixed.
7. Discovery for v2.x devices fixed.
8. Fixed crash when commands contained channels that were no longer valid.
9. Fixed issue where sometimes the front panel USB would not connect to Pro CONSOLE.

RELEASE 8.6.2018

Version Details

1. Pro CONSOLE® Software – v6.0.21.0 (new)
2. CONVERGE Pro 2 Firmware - v5.0.38.0 (new)
3. CONVERGE Huddle Firmware - v1.0.17.0 (new)
4. Beamforming Microphone Array 2 Firmware - v1.0.3.12 (same as last release)
5. USB Expander Firmware - v1.0.2.5 (new)
6. GPIO Expander Firmware - v1.0.2.6 (same as last release)
7. DIALOG™ 20 Firmware – MDO: 2.3.5.2, RXM: 2.0.4, RXS: 1.5.0, MUX: 3.4, TX: 1.2.9 (new)
8. Touch Panel Controller Firmware - v1.0.0.7 (same as last release)

New Products Added

1. CONVERGE Huddle
2. CONVERGE Pro 2 128VT
3. CONVERGE Pro 2 128VTD
4. CONVERGE Pro 2 48VT
5. CONVERGE Pro 2 48VTD (Not fully supported yet)

New Features Added

1. Pro CONSOLE software replaces CONVERGE Pro 2 CONSOLE and provides support for both CONVERGE Huddle and CONVERGE Pro 2 products (look for new icon and new program name). The user has the option to choose CONVERGE Huddle product only or CONVERGE Pro 2 products only or both, during installation and after installation.
2. Added Clear All Routes button in FlowView.
3. Added ability to change Locate timeout value.
4. Added ability to sort by device in Reference Matrix.
5. Dante can now be configured with a static IP address.
6. DIALOG 20 Receiver's firmware can be upgraded using Pro CONSOLE software, when the receiver is connected to CP2 through P-link. The Receiver must have firmware v1.7.4 or later.

Bugs Fixed

1. Fixed a random issue related to hosted VoIP service's inbound call locks up.
2. VoIP Mode is set correctly when enabling Skype For Business.
3. Mute state of a crosspoint is retained while toggling through crosspoint types.
4. Long distance P-Link mode is enabled after loading a project.
5. Improvements in discovering devices.
6. Relative gain commands update correctly in Pro CONSOLE.
7. Updates to Push-to-Talk (PTT) setup.
8. Other minor bugs.

Additional Details

1. Pro CONSOLE replaces CP2 CONSOLE. The system won't allow you to install both CP2 CONSOLE software and Pro CONSOLE software in the same PC.
2. The project files created with CP2 CONSOLE software are compatible with the new Pro CONSOLE software.

RELEASE 4.20.2018

Version Details

1. CONVERGE Pro 2 CONSOLE™ Software - v5.1.10.0 (same as last release)
2. CONVERGE Pro 2 Firmware - v5.0.35.0 (new)
3. Beamforming Microphone Array 2 Firmware - v1.0.3.12 (same as last release)
4. USB Expander Firmware - v1.0.2.4 (same as last release)
5. GPIO Expander Firmware - v1.0.2.6 (same as last release)
6. DIALOG™ 20 Firmware - RXM: 1.7.4, RXS: 1.4.5, MUX: 2.7, TX: 1.2.8 (same as last release)
7. CONVERGE Pro 2 Touch Panel Controller Firmware - v1.0.0.7 (new)

Bugs Fixed

1. Incoming RTP streams withptime value not set to 20 msec play incorrectly in CP2 VoIP units
2. VoIP Phone lines 3 to 5 do not audibly react to MUTE or GAIN changes in CP2 VoIP Units
3. Improved Wi-Fi performance with a required image update in the Touch Panel Controller

Note: Contact ClearOne to update the image.

1. Minor bug fixes and enhancements in the Touch Panel Controller

RELEASE 3.8.2018

Version Details

1. CONVERGE Pro 2 CONSOLE™ Software - v5.1.10.0
2. CONVERGE Pro 2 Firmware - v5.0.33.0
3. Beamforming Microphone Array 2 Firmware - v1.0.3.12
4. USB Expander Firmware - v1.0.2.4
5. GPIO Expander Firmware - v1.0.2.6
6. DIALOG™ 20 Firmware - RXM: 1.7.4, RXS: 1.4.5, MUX: 2.7, TX: 1.2.8
7. CONVERGE Pro 2 Touch Panel Controller Firmware - v1.0.0.2

Note: DIALOG 20 firmware and Remote Software are not included in CONSOLE software for download; they must be downloaded separately. The DIALOG 20 Remote Software application must be used to update the DIALOG 20 firmware.

New Features Added

1. Built-in Skype for Business (S4B) client in CONVERGE Pro 2 48V, 128V, and 128VD units.
2. Skype for Business Dialer App for CONVERGE Pro 2 Touch Panel Controller with support for Dialpad, Contact Management, Call Control, Call Log, and Meeting support.
3. CONVERGE Pro 2 Touch Panel Controller updater in CONVERGE Pro 2 CONSOLE - allows the Touch Panel Controller to be field upgraded to the latest firmware supporting Launcher, Skype for Business Dialer App, and Telco/VoIP Dialer App.
4. The ClearOne CONVERGE Pro 2 Touch Panel Controller Launcher application in the Touch Panel Controller allows the user to start the Telco/VoIP Dialer App or the Skype for Business Dialer App.
5. DIALOG 20 Wireless Mics configuration supports Wideband and Narrowband configuration.

Bugs Fixed

1. GPIO Expander bug fixes and improved response time
2. Mitel VoIP interoperability improvements
3. VoIP stability improvements
4. General stability improvements
5. Site File conversion fixes from version 3
6. Feedback Eliminator fixed node depth fix
7. Correctly adjust for Daylight Savings Time

8. RAMP command responds now responds with GAIN (no longer responds with RAMP)
9. Gateway and DNS fields are independent again
10. CONSOLE uninstaller is signed

RELEASE 12.20.2017

Version Details

1. CONVERGE Pro 2 CONSOLE™ Software - v5.0.18.0
2. CONVERGE Pro 2 Firmware - v5.0.13.0
3. Beamforming Microphone Array 2 Firmware - v1.0.3.12
4. USB Expander Firmware - v1.0.2.4
5. GPIO Expander Firmware - v1.0.2.4
6. DIALOG™ 20 Firmware - RXM: 1.7.4, RXS: 1.4.5, MUX: 2.6, TX: 1.2.8

New Products

GPIO Expander Unit

New Features Added

1. Long Distance P-Link Mode for Beamforming Microphone Array 2 (see cable and power requirements)
2. Support for up to 6 Beamforming Microphone Array 2's on one P-Link chain (see requirements)
3. Additional feature support in Dialog 20 via P-Link

Bugs Fixed

1. Discovery is removed on the VoIP port
2. VLAN addresses are using the same MAC address as the VoIP port
3. Partitions not activating if they are empty
4. Labels are clipped in the Channel Properties
5. CP2 shows that it has no Gateway when it is set for static and using VLAN
6. CONSOLE showing BMA2's using C-Link channels
7. HOOK Enable make no audible changes
8. VoIP TX values change to VoIP Rx in macro commands
9. Enabling FBE on process channel 5-8 cause DSP crash
10. Device names longer than 24 characters cause firmware crash
11. MinSE and Session Expires does not have values above 65535
12. VoIP failing to register when network is changed
13. Having a comma in a file name prevents the pccp2 file from being retrieved
14. Long Macros are cut short when loaded to boxes
15. Downgrading firmware does not default boxes
16. Failed to update live values due to no active partition
17. GATE command does not work with Box labels
18. Disabling VLAN may cause VoIP task to crash
19. BMA2's showing as NA in only one partition setup.

20. VoIP channel labels are not enforcing unique labels
21. USB not passing audio when unplugged and re-plugged multiple times
22. Check for Updates now indicates where the files are being downloaded
23. Setting channel names to NA breaks the channels
24. VOIPUPDATE is preformed after a network change

Known Issues

1. If you are enabling/disabling VLAN you may need to power cycle your units after loading a configuration file.
2. If units are at default they will reset after the first load of a configuration.

Long Distance P-Link Mode Cable and Power Requirements

1. Up to 3 Beamforming Microphone Array 2's. Cannot have other P-Link devices in the chain--only BMA2's. In long distance mode the total P-Link channel count is reduced from 16 channels down to 3 channels.
2. 650 feet (200 meters) maximum cable length between any two devices. Includes the CP2 and BMA2's.
3. Cable must be CAT6, 550 MHz, 23 awg, solid conductor cable. Do not use copper clad aluminum (CCA).
4. PoE Injector must be a 56V, Mode B/Midspan injector. The PoE must connect to either the first BMA2 or the CP2 with a short CAT6 cable.

Additional Beamforming Microphone Array 2 Requirements

You can connect up to 6 BMA2's on one P-Link chain if you have two CP2 units that support the BMA2. CP2 units that support BMA2's are 128, 128D, 128V, 128VD, 128T, 128TD, 48T, 48V, and 120. For every CP2 unit you can have up to 3 BMA2's with a maximum of up to 6 BMA2's on any one P-Link chain.

RELEASE 10.24.2017

Version Details

1. CONVERGE® Pro 2 Firmware - v4.5.45.0

Bugs Fixed

1. VoIP related
2. GPIO related

RELEASE 10.9.2017

Version Details

1. CONVERGE Pro 2 CONSOLE™ Software - v4.0.33.0
2. CONVERGE Pro 2 Firmware - v4.5.40.0
3. Beamforming Microphone Array 2 Firmware - v1.0.2.11
4. USB Expander Firmware - v1.0.1.12
5. DIALOG™ 20 Firmware - RXM: 1.6.5, RXS: 1.4.1, MUX: 2.3, TX: 1.2.8
6. WS800 & DIALOG 20 Remote Software - v3.1.2.14

New Features Added

1. Conversion works from version 3.x project file to the latest version of CONSOLE Software.
2. User is prompted to upgrade firmware to compatible latest version.
3. Individual Channels in a Group now correctly Ramp in parallel.
4. Improved P-Link Device configuration performance and communications.
5. Improved synchronization between Presets.
6. View logs button added.
7. Custom References now work on all output channels of the CONVERGE Pro 2 (CP2) 012 model.
8. SNMP Traps for Safety Mute and Resets now function.

Project file Conversion Scenarios not supported that cause a warning message:

1. ClearOne does not support:
 - a. pushing a configuration to Firmware (FW) v3.x or older.
 - b. viewing or changing settings on FW v3.x or older.
3. The user is informed, when connecting to a V3 box that they can save the on-board project and convert it to V4, and to upgrade his device's firmware to the latest, compatible version. Specifically in this release, when using CONSOLE V4 to connect to a system or stack running V3 firmware, the following message is shown: "Project incompatibility. The stack is using an older version of the firmware. Use the Admin area to retrieve the project file and save it to your local drive. To convert the project file, open it, and resave it."

Upgrading from the 3.x release to the new 4.x release:

1. ClearOne supports:
 - a. Connecting to FW v3.x, retrieving the configuration file, and saving it to the hard drive. The file will still be in v3.x format.
 - b. Opening a v3.x file, and converting it to v4.x format when it is saved to the hard drive. The saved v4.x file can now be pushed to a FW V4 stack.
 - c. Connecting to FW v3.x and updating firmware to v4.5.

RELEASE 9.21.2017

Version Details

1. CONVERGE Pro 2 CONSOLE Software - v4.0.23.3
2. CONVERGE Pro 2 Firmware - v4.5.35.0
3. Beamforming Microphone Array 2 Firmware - v1.0.2.11
4. USB Expander Firmware - v1.0.1.12
5. DIALOG 20 Firmware - MUX 2.3, RXM 1.6.5, TXM 1.3.5, TX 1.2.8, RXS 1.4.1
6. WS800 & DIALOG 20 Remote Software - v3.1.2.11

Note: DIALOG 20 firmware and Remote software are not included in CONSOLE software for download. They have to be downloaded separately.

New Products Added

1. CONVERGE Pro 2 48V DSP unit
2. CONVERGE Pro 2 012 DSP unit
3. USB Expander for CONVERGE Pro 2

New Features Added

1. CONVERGE Pro 2 (CP2) VoIP units (128V, 128VD, 48V) can be configured to support up to 5 VoIP Phones. The number of concurrent calls per phone is based on how many are enabled. Refer the following table for details:

VoIP Phones Enabled	Maximum Number of Concurrent Calls
1	5
2 (default)	5
3	4
4	3
5	2

2. CP2 48V unit has two Ethernet ports. One port for VoIP and another port for Configuration & Control. Voice traffic can be routed to the Ethernet port or the VoIP port based on configuration.
3. CP2 supports DIALOG 20 Wireless Microphone Receiver as a P-Link device. P-link carries power, audio, control.
4. CONSOLE software has an integrated configuration option for DIALOG 20 Wireless Mic system.
5. CP2 supports changing Telco settings while connected live.
6. CP2 supports changing Gate Group settings while connected live.
7. CP2 supports changing VoIP Phone settings while connected live.
8. CP2 and CONSOLE supports Locate button and LED, now functions during discovery and after connection.
9. CONSOLE software has an integrated log viewer that includes VoIP logs.
10. CONSOLE software provides additional network information (IP Address, MAC, Gateway address) available for Ethernet port.
11. CP2 units across subnets will be discovered, if there is a route in between the subnets AND if the company's IT department allows UDP broadcast OR mDNS broadcasts across the subnets.
12. If a PC running with latest CONSOLE software and firmware is connected with live CP2 units, then it will check and alert if new updates are available for CP2 units.
13. Various bug fixes in both Software and Firmware.

Limitations

1. CONSOLE version 3.x will not discover units with newer 4.x firmware.
2. You cannot use site files created in CONSOLE version 3.x or earlier. If you have an existing system you will need to recreate your site file in CONSOLE version 4.0.23.3.
3. New products CP2 48V, CP2 012, USB Expander and DIALOG 20 require CONSOLE v.4.0.23.3 or later.
4. New products 48V and 012 require firmware version 4.5.x.x. They cannot be downgraded to version 3.x.
5. The new VoIP units with the dedicated VoIP port can only have one gateway address and one set of DNS addresses. If using the VoIP LAN, then the Gateway and DNS are derived from the VoIP LAN settings.
6. FlowView™ may not draw lines correctly on the first view.
7. Not more than 3 units of same peripheral devices can be connected in the same P-link chain. For example,

- 4 BFM2 units can't be connected in the same P-link chain even if 2 applicable CP2 units are connected through C-link.
8. DIALOG 20 Receiver must be upgraded to its latest firmware using Remote Software application. At this time, CP2 P-link does not support Firmware upgrade for DIALOG 20 Receiver.
 9. DIALOG 20 firmware and Remote software are not included in CONSOLE software for download. They have to be downloaded separately.
 10. CONSOLE software does not provide narrowband mode for DIALOG 20. Only Wideband mode is supported.

Firmware Upgrade

1. Upgrade all CONVERGE Pro 2 units in your stack to v4.5.35.0 or later. Any units with firmware version 2.0.4.0 must be upgraded without any v3.x firmware or v4.x firmware connected.
2. Upgrade all Beamforming Microphone Array 2 units to v1.0.2.11 or later.
3. Upgrade all USB Expander units to v1.0.1.12 or later.
4. Upgrade all DIALOG 20 units to the latest firmware. At this time DIALOG 20 upgrades must be done via USB using the WS800 & DIALOG 20 Remote Software. This device's firmware to the latest, compatible version. Specifically in this release, when using CONSOLE V4 to connect to a system or stack running V3 firmware, the following message is shown: "Project incompatibility. The stack is using an older version of the firmware. Use the Admin area to retrieve the project file and save it to your local drive. To convert the project file, open it, and resave it."

Upgrading from the 3.x release to the new 4.x release:

1. We support:
 - a. Connecting to FW v3.x, retrieving the configuration file, and saving it to the hard drive. The file will still be in v3.x format.
 - b. Opening a v3.x file, and converting it to v4.x format when it is saved to the hard drive. The saved v4.x file can now be pushed to a FW V4 stack.
 - c. Connecting to FW v3.x and updating firmware to v4.5.

SALES AND INQUIRIES

Headquarters

5225 Wiley Post Way Suite 500
Salt Lake City, UT 84116

Headquarters

Main: +1.801.975.7200

Sales

Tel: +1.801.975.7200
sales@clearone.com

Tech Support

Tel: +1.801.974.3760
audiotechsupport@clearone.com